Request For Proposal (RFP) No. FMC733-26-02
For Stott Reservoir Joint Sealant Removal and Replacement

Addendum #2 – November 11, 2026

To bidders under RFP No. FMC733-26-02 for "Stott Reservoir Joint Sealant Removal and Replacement.

Notice is hereby given that RFP No. FMC733-26-02 for "Stott Reservoir Joint Sealant Removal and Replacement" of the East Bay Municipal Utility District has been revised as set forth below.

1. Appendix A will be provided to all vendors that attended the bid walk on November 9, 2026, and has been included in the RFP under this addendum. Sampling performed by the District shows that there is Asbestos in joint sealants and Crystalline Silica on the ladder and overflow valve. Vendor is expected to verify, through their own sampling, the presence of these materials prior to sorting into drums.

2. Abrasive blasting and coating does not include the center vent.

Contact Tracy Barrow with any questions or if any additional information is required:

Office (510) 287-0627, or email: tracy.barrow@ebmud.com

THIS ADDENDUM MUST BE SUBMITTED WITH THE UPDATED PROPOSAL FORM.

Tracy Barrow
Construction and Maintenance Scheduler