## **Sample Rebate Requirements**

The following are required to be submitted for the Pilot Spring Irrigation Repairs Rebate. Rebates are not guaranteed. For full program rules and eligibility visit ebmud.com/rebates.

## Submit with your application:

1) Photo of irrigation controller showing valve wiring.



## Submit once your repairs are complete:

1) Copy of final invoice showing itemized repairs per station and total project cost (inspection report/workorder with itemized receipt may be accepted on a case-by-case basis).



2) Copy of proposal or inspection report that includes qualified irrigation repairs and costs per station.

F	lepairs Proposal		
Marten Condenses Accordation Address 123 Address Oadcard, CA 194502 Marce Spring Irrigation Repairs	Contact To Billing Address	Continent Management Services Name goeshore 1234 Main Sireet Oaktavic GA (IEBD)	
Name Spring Ingulari Hopars Description Make repairs to existing ini	galian		
	Scope of Work - Contr	uller A	
tas ministrativentiplica			Tele
			\$1,200.00
Rainbird 1800 6" installed- i	App-up Spray Head		
Harter PCP 4" Installati-Re	ior lessis		
Hunter PGP 12" Installed- R	olor heads		
Lakeral line break Repaired			
Heplace bad solenoid on va	10		
Replace duraged or boles	norris.		
			\$735 M
Huda PGP 12" Include P	tainy Maanta		
Replace damaged or broker	nozzies		
			\$1,000.00
Rainbird 1800 6* Installed- R	App-up Spray Head		
Rainbird 1800 12" installed	Pap up Spray Head		
Raise spray heads that are	currently below grade		
apatra .			\$260 M
Rainbird PEB (plastic) 1 %*	Installed- Valves		
		Total Price	\$3,345,00
-	Raise spray heads that are o	Radebid HER UT Indultid-I Pap of Sprzy Hoad Plate sprzy heads that are currently below grade In Radebid PEB (statte) 1 %" installed-Valves	Raise spray heads that are currently below grade Raineard PEB (plante) 1 %" installed: Valves

2) Photos (5-7) before/after of completed repairs.

mers As	modulum Management Services ceet	INVOICE Curtomer#1 12345 fervairab 67 fervairab 68 fervairab 67 fervairab 68 fervairab 68 curt FO#: each 68 ferra
QTY	Description	Amount
	Zama 1,2,3 Reputa	
æ	Rainblind 1900 G* Installed- Pop-up 3pray I lead	
	Hunter PGP 4" Indultes' Rota heads	
	Humber PGP 17" Installed-Rober treads	
1.00	Lalean me ovan Heparea	
m	Replace bad advected on value	
	Replace dansaged or brains nazzles	
		\$1,200.00
	Zona 4 Repairs	
111	Hunter PGP 12" Installed- Robin Insula	
	Heparce Gamages of Dicition Instation	
		\$235.00
	Zara 2,6,7 Again	
	Rainbird 1900 6" installed- Pop-up Spray Head	
500	Rainbird 1800 12" Indailad- Pop-up Spcay Haad	
80=	Raise spray heads that are currently below grade	
		\$1,600.00
	Ballary Controller Repairs	
m	Raintind PEB (plantic) 1 %" installed- Valves.	
		\$350.00
		Total Price \$3 385 00
		Total Price \$3,385.00
		en 207 AG
	Total	invoice amorant \$3,385.00

Water Conservation | 1-866-403-2683 www.ebmud.com/watersmart