## **Sample Rebate Requirements**

The following are required to be submitted for the Pilot Spring Irrigation Repairs Rebate. Rebates are not guaranteed. For full program rules and eligibility visit ebmud.com/rebates.

## Submit with your application:

1) Photo of irrigation controller showing valve wiring.



## Submit once your repairs are complete:

1) Photos (5-7) before/after of completed repairs.



2) Copy of proposal or inspection report that includes qualified irrigation repairs and costs per station.

		Irrigation	n Spring Start U	Jp .				
	Repairs Proposal							
	Property Name Property Address Project Name	Conference Association 123 Address Oaldand, CA 19802 Spring Imgalian Repairs	Contact To Dilling Address	Continuer Management Services Name geeshore 1224 Main Street Caldand, CA (1990)				
	Project Description	Make repairs to existing inigation						
		Sco	ope of Work - Contr	oller A				
GIT	United by	and a characterization			Tela			
lam 1,2,3	-				\$1,700 00			
3.00	EACH	Ranbird 1800 6" Installed- Pop-up Spray Head						
1.00	6ADH	Harter PCP C Indultet- Halar Insula						
5.00	EACH	Hunter PGP 12" Installed- Rotor heads						
100	5ACH	Laleral line break Repaired						
1.00	EACH	Replace cad sciencid on vave						
7.00	ENDI	Replace damaged or lockes name	in.					
Zane 4 Re	pairs.				\$735.M			
200	ENDI	Hudar PCP 12" Incluing Role in						
3.00	EACH	Replace damaged or broken nozzi	85					
Zarno 5,6,7	Superior 1				\$1,000.00			
7.00	EACH	Rainbird 1800 6* Installed- Pop-up	Spray Head					
15.00	ENCH	Rainbird 1808 12" Installed- Pap up Spay Head						
18.00	EACH	Raise spray heads that are current	By below grade					
talkey De	and solice Happens				\$240 M			
1.00	EACH	Rainbird PEB (plastic) 1 %* install	ed-Valves					
				Total Price	\$3,305.00			

2) Copy of final invoice showing itemized repairs per station and total project cost (inspection report/workorder with itemized receipt may be accepted on a case-by-case basis).

Landscape Co. INVOICE Creduters Associations of U-Castomer Management, Structures Oakland, CA 00000			87.4
QTY	Description		Amount
	Zare 1,2,3 Repairs		
3.00	Robinited 1900 G* Indefinited- Pop-up Spray Head		
100	Hunter PGP 4" Installed-Rober Insats		
609	Hunley PGP 17" Installed- Roley Insuls		
1.00	Laiesa ne men Hesares		
1.00	Replace bad advected on value		
7.50	Replace damaged or lenken reactes		
			\$1,200.00
	Zarn 4 Repairs		
2.00	Hunter PSP 17 Installed- Refer Installe		
3.80	Regiance damages or builden mozzles		
			\$235.00
	Zorn 3,6,7 Repairs		
700	Rainblid 1900 6" installed- Pop-op Spray Head		
1500	Rainbird 1800 12" Instalket-Pap-up Spray Haad		
16.00	Raise gray heads that are currently before grade		
			\$1,600.00
	Ballery Cunicalar Auguire		
1.00	Rainblid PEB (stadle) 1 % installed- Valves.		
			\$950.00
		Total Price	\$3,385.00
	Te	tal invoice amount	\$3,385.00

Updated January 2025



## Water Conservation | 1-866-403-2683 www.ebmud.com/watersmart